

**SP COMBINE WIRING HARNESSSES
PRIOR TO A9960**

M9665

PART NO.	DESCRIPTION	QTY	COMMENT
16224	Harness, Engine; SP (modified JAH144954)	1	See Note below
16149	Harness, R.H. Main '95 (1st version)	1	
16150	Harness, L.H. Main '95 (1st version)	1	
AH125036	Harness, Wire; St Walker Warning	1	

M9865

PART NO.	DESCRIPTION	QTY	COMMENT
16224	Harness, Engine; SP (modified JAH144954)	1	See Note below
16246	Harness, 10% Varia. Speed Pigtail	1	
16264	Harness, '98 R.H. Main (JAH155916)	1	
16293	Harness, '99 L.H. Main w/Var.Spd. Pigtail	1	Replaced 16263

A9900, A9905-4

PART NO.	DESCRIPTION	QTY	COMMENT
16224	Harness, Engine; SP (modified JAH144954)	1	See Note below
16246	Harness, 10% Varia. Speed Pigtail	1	Not shown in parts catalog
16264	Harness, '98 R.H. Main (JAH155916)	1	
16293	Harness, '99 L.H. Main w/Var.Spd. Pigtail	1	

M9965A

PART NO.	DESCRIPTION	QTY	COMMENT
16224	Harness, Engine; SP (modified JAH144954)	1	See Note below
16246	Harness, 10% Varia. Speed Pigtail	1	Not shown in parts catalog
16264	Harness, '98 R.H. Main (JAH155916)	1	
16293	Harness, '99 L.H. Main w/Var.Spd. Pigtail	1	

Note:

It is advantageous for the customer to purchase an AH144984 from John Deere. All combine functions excluding 10% engine throttle control will work with this harness. To activate 10% function, add Amadas Kit #71283 (jumper wire assembly and instructional drawing).